# Prevention and prediction drive new solutions

IN SHIPBOARD FIRES PREVENTION IS BETTER THAN CURE. WHILE FIRE-MITIGATING TECHNOLOGY IS ADVANCING ON ALL FRONTS, IMO IS GETTING TOUGHER ON INSPECTION AND MAINTENANCE

BY SELWYN PARKER

There have been a number of significant fire incidents on roro passenger vehicle decks since 1994 and there is no sign of these diminishing. here are still too many shipboard fires, says IMO. Fires on board passenger ships, and especially on roro ferries, occur far too frequently, according to a series of studies by IMO safety experts. They cite a total of 73 fires on roro passenger ships between 1994 and 2011.

And, of course, others have happened since then. One of the most recent was a ferry, *PeeJay V*, which caught fire just off the New Zealand coast in January 2016 and burned down to the waterline. Fortunately, none of the 57 people on board died.

IMO concludes: "There have been a number of significant fire incidents on roro passenger vehicle decks since 1994 and there is no sign of these diminishing. Since 2002 there has been a very serious incident every other year, resulting in six constructive total losses."

According to IMO's investigations, these fires were triggered by a variety of causes ranging from electrical problems in parked vehicles to engineroom events. The blaze on PeeJay V is thought to have started in the galley. But, disturbingly, follow-up analysis revealed that failures in the maintenance and inspection of firefighting tools such as sprinklers contributed significantly to the frequency of fires. Once they had started, the fires were not contained as rapidly as they should have been.

Although IMO's overriding consideration is human life, there is also a commercial imperative involved in fire prevention. The cost of an onboard fire is put at around US\$200,000 a minute.


As a result of its findings IMO is cracking down on operators and demanding more frequent inspections and documented evidence of routine maintenance. The safety authorities are particularly concerned about older ships. "Consideration should be given to identifying improvements that can be made to the fireprotection standards applied to roro passenger ships constructed before 1 July 2010 to enhance their survivability and safe return to port in the event of a vehicle deck fire," a 2014 report noted, pointing out that such vessels could remain in service for the next 20 years or more.

A test on Bahamas-registered vessels supported IMO's concerns. It revealed an alarmingly high failure rate of automatic sprinklers on passenger ships – in some cases more than 50 per cent. The importance of the reliability of sprinklers is obvious. A typical passenger ship will have as many as 6,000 sprinklers in accommodation and service areas.

The resulting warnings highlighted the value of disciplined inspection and maintenance. As one report noted, interim fire-safety measures must immediately be put in place when thorough testing reveals high failure rates. "These [measures] comprise increased fire patrolling activities and procedures where, in the event of a confirmed fire, the automatic sprinkler system may be started remotely from the bridge and operated at maximum operating pressure," the authors said.

The contradiction is that while failures in routine maintenance lie behind many fires, the fire-prevention industry is devising increasingly clever solutions to prevent events – or at least reduce the damage from them. Water mists, for example, are

## Thermal characteristics of PROMAGUARD<sup>®</sup>, thickness of 10mm



Third-party tests show how layers of Promaguard suppress thermal conductivity and delay the onset of a fire

becoming more powerful and faster-acting, as in the case of Finland-based Marioff Corp's latest HI-FOG 3000 system launched in early 2015.

As soon as the ambient temperatures hit a pre-designated threshold, the bulb breaks and a continuous spray of water is distributed through concealed pipes, over a wider area than previous models. And because the system uses pure water, it can be activated without any risk to human life. As Marioff points out, the firefighting can start without the space having to be evacuated first.

As well as being more powerful, the latest sprinkler systems are more compact. Among other advantages this means they can be easily retrofitted without destroying the aesthetic integrity of cabin interiors. For instance, the HI-FOG 3000 has narrow tubing, and smaller pump units and water tanks. Similarly, the space-saving Minifog Marine XP sprinkler developed by German manufacturer Minimax uses up to 90 per cent less water. Despite this, one unit can protect an area of up to  $32m^2$ .

At the same time, heavy science has gone into the development of passive protection that aims to contain as long as possible the spread of a fire or explosion, but without the need for intervention in the form of sprinklers and other active deterrents. For instance, Promaguard by Belgium-based group Promat is a microporous material that is based on nano-structured, sub-micron, synthetic amorphous silica (SAS).

Combined with other environmentally safe synthetics, SAS particles are formed into long chains that work to block the invasion of solid heat – that is to say, flames. The spaces in the chain are so small that they are able to eliminate the conduction of most of the gaseous heat. Simultaneously, materials known as mineral oxide pacifiers inhibit infra-red radiation.

SAS has proved spectacularly successful. Made into light and thin strips of cloth, Promaguard was quickly adopted by the aviation industry where it was applied in places of high fire risk such as the radome, engine and exhaust, and galley. And now it is being used on a wide scale in shipping.

Aiming to beat the Solas A60 fire-rating standards for a ship's safe return to port, Promat developed a year-long project for the marine industry that ended successfully in June 2014. By then a series of stringent, third-party monitored tests had established that 15mm thick layers of Promaguard were able to exceed A60 while Promaguard combined with Ultimate, an Isover insulation product, could keep a fire at bay for nearly four hours. Even better, these gains could be achieved without any time-consuming and costly fire-resistant alterations to the ship's original design.

Promat's Giorgio Lauro, naval architect and marine segment manager, explained that they were able to prolong the period when a fire is prevented from spreading from 60 minutes to 240 minutes by adding only 15mm lengths of Promaguard on top of an existing standard insulation. The company says the layers can be applied with equal effectiveness on aluminium, steel and fibreglass decks and bulkheads. Promaguard is also finding favour in operational areas such as control rooms and offices where drench systems can ruin valuable electronic equipment and intellectual property.

Meanwhile, the engineroom remains by far the most common source of a fire on every kind of vessel including passenger ships, accounting for between 50 and 70 per cent of all fires and explosions. Mohit Sanguri, an authority on fire prevention currently working with Dynacom Tankers Management, pointed out in a recent study: "The engineroom of a sea going ship is a highly fire-prone area." Given that it usually contains tanks that are full of different kinds of hot oils and chemicals, some of which runs through kilometres of piping at pressures as high as 1,200 bar, this is hardly surprising.

While conscientious maintenance of fire-prone areas in the engineroom remains the best prevention – this being the primary responsibility of the fire-safety officer – explosions can be triggered by a variety of less easily detected factors such as material fatigue and failures in automation. Most modern enginerooms bristle with fire-detection systems such as heat, flame and smoke detectors that are monitored from the bridge on a master control panel. Secondary systems are installed in the engineroom. And most enginerooms are equipped with high powered sprinklers.

But the ideal solution is clearly to predict the fire or explosion – that is, before it occurs – and thus head it off. This is the idea behind the US\$100,000 LAS-10 system produced by Denmark manufacturer Daspos. Designed for the open enginerooms on big ships, the LAS-10 (leakage alarm system) continuously analyses the atmospheric air for any dangerous density in hazardous oil fumes and gases. If the system detects that densities have reached intolerable levels, it alerts the crew. Validated by the Danish Technological Institute, LAS-10 is being proven on passenger and other vessels.

But if a fire does break out in the engineroom despite precautions, nobody has yet found an alternative to the classic fire extinguisher – albeit much modified. Fast-acting, they are highly effective for dousing localised blazes and explosions before they spread into full-scale conflagrations.

Filled with carbon dioxide  $(CO_2)$ , dry chemical powder or foam, according to the requirement, extinguishers should be placed at specific points in the engineroom.

And, more traditional again, the sand box remains an effective fire-fighting tool after all these years. First used on vessels that were powered by combustion engines, the sand box is placed near the boiler. If a minor fire breaks out, sand is thrown onto the flames.

But when none of the above work, the last resort is the dedicated  $CO_2$  room where this gas is stored under high pressure. The oxygen-replacing  $CO_2$  is deployed only when the fire has taken hold. Mr Sanguri added: "The  $CO_2$  is released in the emergency situation of a fire out of control, after evacuation of the engineroom by the chief engineer on the order of the master of the ship."

It has not yet been established how to deal with ethanoltriggered fires, which are more likely given the growth in ethanolpowered fleets. "No one really knows what happens in the event of a cistern fire involving ethanol, or how best to extinguish it," reported Björn Sundström, head of the department of fire technology at SP Technical Research Institute of Sweden, in February. But his department is working on it. The laboratory is running a project called Etankfire (ethanol tank fire-fighting) that is studying the special characteristics of an ethanol-triggered blaze. It hopes to come up with some answers shortly.

Finally, IMO's reports highlight a common problem in firefighting on board ships—once a blaze starts, things start going wrong. In seven of the 14 cases studied of roro fires, drenchers were unsuccessful or partially successful. In the *Lisco Gloria* fire in October 2010 the system did not deliver any water at all. And when *Vincenzo Florio* went ablaze in July 2004, a power black-out delayed the activation of the foam fire-fighting system installed on the vehicle decks. As a result the blaze raged for ten days.

If US\$200,000 a minute is a reliable estimate of the damage a fire causes, it is not surprising that *Vincenzo Florio* required extensive repairs. *PST* 

### 73 FIRES

ON RORO PASSENGER SHIPS BETWEEN 1994 AND 2011

SINCE 2002 THERE HAS BEEN A VERY SERIOUS INCIDENT EVERY OTHER YEAR, RESULTING IN SIX CONSTRUCTIVE TOTAL LOSSES

## THE COST OF AN ONBOARD FIRE IS PUT AT AROUND US\$200,000 A MINUTE

A TEST ON BAHAMAS-REGISTERED VESSELS REVEALED A HIGH FAILURE RATE OF AUTOMATIC SPRINKLERS ON PASSENGER SHIPS – IN SOME CASES MORE THAN 50 PER CENT.

THE ENGINEROOM ACCOUNTS FOR BETWEEN 50 AND 70 PER CENT OF ALL FIRES AND EXPLOSIONS ON ALL TYPES OF VESSELS

IN SEVEN OF THE 14 RORO FIRE CASES STUDIED DRENCHERS WERE UNSUCCESSFUL OR PARTIALLY SUCCESSFUL (IMO REPORT)





Promat's project showed that it was able to prolong the period when a fire is prevented from spreading from 60 minutes to 240 minutes

## Promat

#### **Belgium / Luxemburg**

**Microtherm NV** Industriepark-Noord 1 9100 Sint-Niklaas Tel: +32 3 760 1980 Fax: +32 3 760 1999 info@promat-industry.com www.promat-industry.com

#### Asia Pacific Headquarters, Malaysia **Promat International**

(Asia Pacific) Ltd. Unit 19-02-01 -Level 2 PNB Damansara No.19 Lorong Dungun - Damansara Heights 50490 Kuala Lumpur Tel: +60 3 2095 5111 Fax: +60 3 2095 6111 info@promat-ap.com www.promat-ap.com

#### Australia

Promat Australia Pty. Ltd.

1 Scotland Road Mile End South Adelaide, SA 5031 Tel: 1800 Promat (776 628) Fax: +61 8 8352 1014 mail@promat.com.au www.promat-ap.com

#### Austria

**Promat GmbH** St.-Peter-Straße 25 4021 Linz Tel: +43 732 - 6912 - 0 Fax: +43 732 - 6912 - 3740 office@promat.at www.promat.at

#### China

**Promat China Ltd.** Room 1507, Building 5 SOHO Xiandaicheng No.88 Jianguo Road Chaoyang District 100022 Beijing Tel: +86 (10) 8589 1254 Fax: +86 (10) 8589 2904 info@promat.com.cn www.promat.com.cn

#### **Czech Republic** Promat s.r.o.

Čkalova 22/784 16000 Praha 6 - Bubenec Tel: +420 2 2439 0811 Fax: +420 2 3333 3576 promat@promatpraha.cz www.promatpraha.cz

#### Denmark

lvarsson Kometvej 36 6230 Rødekro Tel: +45 7020 0482 Fax: +45 7466 1020 info@promat.nu www.promat.nu

#### France

Promat S.A.S. BP 66 Rue de L'Ammandier 78540 Vernouillet Tel: +33 1 3979 6160 Fax: +33 1 3971 1660 info@promat.fr www.promat.fr

#### Germany

Promat GmbH Scheifenkamp 16 40878 Ratingen Tel: +49 2102 493 0 Fax: +49 2102 493 111 mail@promat.de www.promat.de

#### Hong Kong

#### **Promat International** (Asia Pacific) Ltd.

Room 1010, C.C. Wu Building 302-308 Hennessy Road, Wanchai Tel: +852 2836 3692 Fax: +852 2834 4313 apromath@promat.com.hk www.promat.com.hk

#### India **Promat Fire & Insulation**

#### Private Limited

Unit No. 605, 6th Floor, Tower B Global Business Park Mehrauli Gurgaon Road Sector 26, Gurgaon 122 002 Haryana Tel: +91 (0) 124 4346865 info@promat-india.com www.promat-india.com

#### Italy

Promat S.p.A. Via Perlasca 14 27010 Vellezzo Bellini (PV) Tel: +39 0382 45 75 1

Fax: +39 0382 92 69 00 industria@promat.it www.promat-marine.com

#### Japan

#### Promat Japan Corporation

Mitsuiseimei Shinohashi Bldg. 7F, 1-8-11 Shinohashi, Koto-ku Tokvo 135-0007 Tel: +81 333 772 821 Fax: +81 333 782 821 sales@promat.jp www.promat.jp

#### Malaysia

Promat (Malaysia) Sdn. Bhd. Unit 19-02-01 - Level 2 PNB Damansara No.19 Lorong Dungun Damansara Heights 50490 Kuala Lumpur Tel: +60 3 2095 8555 Fax: +60 3 2095 2111 info@promat-ap.com www.promat-ap.com

#### The Netherlands

Promat B.V. Vleugelboot 22 3991 CL Houten PO Box 475 3990 GG Houten Tel: +31 30 241 0770 Fax: +31 30 241 0771 info@promat.nl www.promat.nl

#### Poland

#### Promat TOP Sp. z o. o.

ul. Przecławska 8 03 879 Warszawa Tel: +48 22 212 2280 Fax: +48 22 212 2290 top@promattop.pl www.promattop.pl

#### Russia

Promat Pr. Vernadskogo 84/2 119606 Moscow Tel: +7 (495) 246 01 01 Fax: +7(495) 246 01 92 sales@promat.ru

#### Singapore

#### Promat Building System Pte. Ltd.

10 Science Park Road #03-14 The Alpha - Singapore Science Park II 117684 Singapore Tel: +65 6776 7635 Fax: +65 6776 7624 info@promat.com.sg

#### Slovenia

Trata 50

www.promat-ap.com

#### Promat d.o.o.

4220 Škofja Loka Tel: +386 4 51 51 451 Fax: +386 4 51 51 450 info@promat-see.com www.promat-see.com

#### **South Africa**

#### Marley SA (Pty) Ltd.

44 Industry Road, Clayville Ext. 444 Olifantsfontein, 1666 Gauteng Tel: +27 (0)11 316 2121 promat@marley.co.za www.promat-industry.co.za

#### South Korea **Promat International**

(Asia Pacific) Ltd. (Korea Branch Office)

Room 406, 811-2 - Yeoksam-dong Gangnam-gu 135080 Seoul Tel: +82 70 7794 8216 apromath@promat.com.hk www.promat-ap.com

#### Spain

#### Promat Ibérica S.A. C/Velazquez, 47 - 6° izda 28001 Madrid Tel: +34 91 781 1550 Fax: +34 91 575 1597 info@promat.es www.promat.es

Switzerland

**Promat AG** Stationsstrasse 1 8545 Rickenbach-Sulz Tel: +41 52 320 9400 Fax: +41 52 320 9402 office@promat.ch www.promat.ch

#### **United Arab Emirates**

**Promat Fire Protection LLC** Plot no. 597-921, Dubai Investment Park 2 PO Box 123945 Dubai Tel: +971 4 885 3070 Fax: +971 4 885 3588 www.promatfp.ae

#### United Kingdom

**Promat UK Limited** Unit B1, Broadlands Heywood Distribution Park Pilsworth Road Heywood OL10 2TS Tel: +44 (0) 800 588 4444 Fax: +44 (0) 161 763 0569 sales@promat.co.uk www.promat-marine.com

#### USA

Promat Inc. 1731 Fred Lawson Drive 37801 Maryville Tennessee Tel: +1 865 681 0155 Fax: +1 865 681 0016 sales@promat.us www.promat.us

www.promat.ru